



Solar Panel Mount



2 X 1/4"-20 Stainless Cap Screw
Use thread locker on threads!

SECTION A-A
SCALE 1 : 4

Use 3 X 3"-4" hose clamps to
attach to 2.5" or 3" crane pipe

Required parts:

10 watt solar panel

Mounting rail

2 x 1/4"-20 cap screw, stainless steel

Required tools:

7/16" end wrench

5/16" nut driver OR flat blade screwdriver

Loctite thread locker